

United States Steel Corporation Clairion Works 400 State Street Clairton, PA 15025

October 8, 2012

OCT 2.2 2012

3AP20

Mr. Ed Peresie Department of Air Quality Bureau of Air Pollution Control 301 Thirty-Ninth Street Pittsburgh, PA 15201

U.S. Environmental Protection Agency Region III Air, Radiation & Toxics Division 1650 Arch Street Philadelphia, PA 19103-2029 ATTN: James W. Hagedorn (3AT23)

Mr. Steve Hepler Southwest Region 400 Waterfront Drive Pittsburgh, PA 15222-4745

Department of Justice Department of Environmental Protection Environmental and Natural Resource Division Environmental Enforcement Section P.O. Box 7611 Ben Franklin Station Washington, D.C. 20044 ATTN: David Street, Esq.

Subject:

USS Reference Number: 12-0316 ACHD Reference Number: 15100

600 Claus Plant USS Clairton Works

Gentlemen:

The attached form terminates the subject incident and satisfies the requirements of paragraph IV.8 of the Title V operating permit #0052 as issued on March 27th 2012.

I certify that based on the information and belief formed after reasonable inquiry, the statements and information in this document are true, accurate, and complete. Any questions concerning this matter should be referred to Coleen M. Davis at 412-233-1015.

Sincerely,

Thomas E. Schumacher Acting Plant Manager Clairton Works

NOTICE OF OUTAGE OF EQUIPMENT ARTICLE XXI - SECTION 2108.1

1. USS Reference Number: 12-0316 <u>Termination</u>
ACHD Reference Number: 15100

2. Date & Time of Outage: Date: 09/24/12 Time: 0900 hours

3. Company Name: U.S. Steel Corporation - USS Clairton Works

- 4. Specific Equipment Involved or Affected: 600 Claus Plant
- 5. BAPC Permit Number (if applicable):
- 6. Location: Clairton, PA
- 7. Nature and cause of breakdown: During an approximate 2 week period, the 600 Claus Plant will be unavailable for service to perform general maintenance.

The 600 Claus Unit is a redundant piece of equipment. Gas processing for sulfur removal was handed off to the 400 Claus Unit. Sulfur Plant performance will not be affected. Sulfur emissions will not increase.

- 8. Identification of Emissions:
 - A. Type(s) (CO, NOX, SO₂, Particulates, Hydrocarbons, etc.)
 The 400 Claus Plant will carry the full acid gas flow to the plant. No environmental impact is expected.
 - B. Toxic qualities of each type (including its qualities as an irritant, and its potential for causing illness, disability, or mortality). N/A No environmental impact is expected.
 - C. Amount of each type emitted (or likely to be emitted). N/A
- 9. Measures taken (or to be taken) to minimize length of breakdown and amount of emissions, including shutdown or curtailment (or why it is impossible or impractical to do so).

 Personnel, materials and equipment were on site prior to the start of the outage. The 400 Claus Plant carried the full acid gas flow to the plant.
- 10. Facility back in operation Date: 10/01/12 Time: 1130 hours

Reviewed by ((Cen)), Lucio Date 10-10-12

Senior Environmental Control Engineer Phone: 412-233-1015